

RECALL NOTICE

Bestway AirJet and HydroJet Spa Pumps

AirJet Model Nos: P05333, P05340, P07002, P07003

HydroJet Model Nos: P05511, P07034

Sold from October 2020 – June 2024



The recalled AirJet and HydroJet spa pumps can overheat, posing a fire hazard.

Consumers should immediately stop using the recalled spa pumps and contact Bestway to receive either a free replacement spa pump or a pump refund of CAD \$137 for AirJet spa pumps or CAD \$259 for HydroJet spa pumps.

For additional information, contact Bestway at:

Toll Free: **(888) 943-2396 Mon. – Fri. 8 a.m. to 5 p.m. (ET)**

Online at www.bestwaycorp.ca